

Ship Name: **ACHILLEAS FRANGISTAS**
IMO Number: **7823293**
Date Detained: **09/18/2002**
Port: **Port Everglades, Florida**

Ship Type: **Bulk Carrier**
Flag: **Malta**
Class Society: **Nippon Kaiji Kyokai**
Company(s): Owners, Operators or Managers
AF Maritime Limited
Navipower Compania Naviera

Deficiencies: Code - Category
2025 - Abandon ship drills

Description
Crew unable to demonstrate proficiency in abandon ship drill.

Ship Name: **AIN OUSSERA**
IMO Number: **8220321**
Date Detained: **09/04/2002**
Port: **N. Charleston, South Carolina**

Ship Type: **Bulk Carrier**
Flag: **Algeria**
Class Society: **Bureau Veritas**
Company(s): Owners, Operators or Managers
SNTM/CNAN/UTC

Deficiencies: Code - Category
0720 - Fire fighting equipment

Description
Pumps not available for immediate use. (secondary fire pump inoperative).

Ship Name: **ASIRAT**
IMO Number: **8313063**
Date Detained: **09/12/2002**
Port: **Jacksonville, Florida**

Ship Type: **General Dry Cargo Ship**
Flag: **Malta**
Class Society: **Det Norske Veritas**
Company(s): Owners, Operators or Managers
Sotrans Shipping & Trading
Torridon Shipping LTD

Deficiencies: Code - Category
0220 - Certificates of competency
0110 - Cargo ship safety

Description
Crew certificates not endorsed by flag state.
Insufficient lifesaving provided for crew in accordance with Safety Equipment Certificate.

Ship Name: **BBC FINLAND**
IMO Number: **9210268**
Date Detained: **09/10/2002**
Port: **Baltimore, Maryland**

Ship Type: **General Dry Cargo Ship**
Flag: **Cyprus**
Class Society: **Germanischer Lloyd**
Company(s): Owners, Operators or Managers
Briese Schifffahrts GMBH & Co. KG

Deficiencies: Code - Category
0299 - Other (Crew)

Description
No flag state endorsement on the STCW 95 certificates or documentary proof from the flag state that an application for endorsement to the STCW 95 certificated have been filed.

Ship Name: CALA GALDANA	Ship Type: Vehicle Carrier
IMO Number: 7334125	Flag: Panama
Date Detained: 09/26/2002	Class Society: Panama Maritime Documentation Service
Port: Staten Island, New York	Company(s): <u>Owners, Operators or Managers</u> Antartida Marine Corp., S.A. Pinafore Shipping Company Naviera Zarama S.A

<u>Deficiencies:</u>	<u>Code - Category</u>	<u>Description</u>
	0720 - Fire fighting equipment	Ship stores stowed in the way of numerous portable extinguishers and fire hydrants preventing immediate access to this fire the emergency fire pump.
	0720 - Fire fighting equipment	Emergency fire pump did not start after multiple attempts.
	0720 - Fire fighting equipment	Firemain piping on starboard side wasted and holed.
	0720 - Fire fighting equipment	Fire hydrant located on the lower level cargo deck was removed and the piping was blanked off.
	1499 - Other (Prop. & Aux. Machinery)	#1 ship service generator cooling piping excessively corroded to such an extent that resulted in the generator being out to commission. Temporary repairs, such as coffee cans an duct tape, were fitted to the main diesel engine.
	1110 - Stowage of cargo	Approved cargo securing manual missing.
	0611 - Lifeboat inventory	Lifeboat oars were rotten and broke apart upon handling.
	2545 - Reports/analysis of non-conformities, etc.	Crew unfamiliar with reporting and have not sent non-conformities.

Ship Name: **GLORY STAR**

IMO Number: **8325028**

Date Detained: **09/22/2002**

Port: **Guam**

Ship Type: **Bulk Carrier**

Flag: **Panama**

Class Society: **Nippon Kaiji Kyokai**

Company(s): Owners, Operators or Managers
Yakumo Shipping Inc.
Belden Management Inc.

Deficiencies: Code - Category
1250 - Covers (hatchways

**2510 - Safety and environmental
policy**

0710 - Fire prevention

0950 - Electric equipment in

Description
**Subdivision access panel missing at frame 84,
compromising watertight integrity design of
vessel.**

**Longstanding unresolved deficiencies in
lifesaving cargo provides objective evidence
that a breakdown in the Safety Management
System has occurred. August audit did not
address the 20 discrepancies as
non-conformities. External audit ordered.**

**Explosive-proof covers missing for lights in
cargo tunnel.**

**No. 2 Ships Service Generator (SSDG) fuel
pump leaking excessively.**

Ship Name: **GRAND SPRING**

IMO Number: **9162980**

Date Detained: **09/06/2002**

Port: **Mobile, Alabama**

Ship Type: **Bulk Carrier**

Flag: **Panama**

Class Society: **Nippon Kaiji Kyokai**

Company(s): Owners, Operators or Managers
Sunny Spring Co., Ltd. S.A.

Deficiencies: Code - Category
0220 - Certificates of competency

1430 - Auxiliary engines

0750 - Fire prevention

0936 - Steering gear

**1499 - Other (Prop. & Aux.
Machinery)**

1420 - Cleanliness of engine room

0999 - Other (Safety In General)

1720 - Control of discharge of oil

0999 - Other (Safety In General)

1470 - Insulation wetted through

**1730 - Oily-water separating
equipment**

1470 - Insulation wetted through

Description
**Chief engineer did not maintain minimum
competencies required by STCW95.**

Emergency generator inoperable.

Fire door to engine room will not close.

Hydraulic leak on steering gear.

**Major lube oil leaks on all ship's service diesel
generators.**

**Excessive oil on generators, main diesel
engine, pumps, and in bilges.**

Major leak on lube oil purifier

Major leak on fuel oil circulation pumps.

Unauthorised hold backs on all fire doors.

**Sheathing on main diesel engine fuel oil lines
cracked and wasted.**

Oily water separator inoperable.

Oil soaked lagging on boiler fuel/oil piping.

2020 - Fire drills

Crew unable to demonstrate proficiency in a fire drill.

2025 - Abandon ship drills

Crew unable to demonstrate proficiency in an abandon ship drill.

Ship Name: **HYBUR STAR**

Ship Type: **General Dry Cargo Ship**

IMO Number: **5022302**

Flag: **Panama**

Date Detained: **09/17/2002**

Class Society: **Panama Maritime Documentation Service**

Port: **Miami, Florida**

Company(s): Owners, Operators or Managers
St. Maarten Reefers Limited

Deficiencies: Code - Category
1499 - Other (Prop. & Aux. Machinery)

Description
Installed emergency fire pump has temporary rubber hose soft patch instead of piping on discharge side.

0230 - Number/composition (manning)

Vessel not manned IAW Safe Manning Certificate.

0630 - Launch arrangt. for survival craft

Foundation for starboard forward davit is wasted.

2020 - Fire drills

Crew unable to demonstrate proficiency in fire drill.

0735 - Personal equipment - fire fighting

Breathing apparatus for fireman's outfit inoperable.

0999 - Other (Safety In General)

Deck drain pipe running through steering compartment has large holes.

0999 - Other (Safety In General)

Galley drain pipe running through steering compartment has large holes.

0999 - Other (Safety In General)

Salt water pipe for main engine has temporary soft patch repairs by elbow.

1499 - Other (Prop. & Aux. Machinery)

Port generator has PVC on inboard side instead of metal pipe.

Ship Name: **ISLAND INTREPID**

IMO Number: **7033161**

Date Detained: **09/05/2002**

Port: **Miami, Florida**

Ship Type: **General Dry Cargo Ship**

Flag: **Saint Vincent and the Grenadines**

Class Society: **Govt of Listed Flag**

Company(s): Owners, Operators or Managers
Island Intrepid Ltd

Mercator Ship Management, S.A.

Deficiencies:	<u>Code - Category</u>	<u>Description</u>
	1299 - Other (Load Lines)	Main deck between superstructure and cargo hatch wasted with holes leading to engine room.
	0111 - Cargo ship safety	Vessel cargo ship safety construction certificate expired as of 8-24-02.
	1299 - Other (Load Lines)	Vessel overdue drydock by almost 1.5 years.
	1299 - Other (Load Lines)	Manhole covers on cargo hatches missing bolts and some wasted,
	1299 - Other (Load Lines)	Wasted cap on WTF P pipe located amidships on port side and other sounding tube caps missing.
	1240 - Cargo and other hatchways	Cargo hatches missing numerous dogs.
	1299 - Other (Load Lines)	Gooseneck on port side just forward of amidships is holed.
	1299 - Other (Load Lines)	Pipe leading from port side of bosun stores to forward cargo hold is wasted and holed.
	1299 - Other (Load Lines)	Hawsepipe wasted on port side at overhead in bosun stores.
	1299 - Other (Load Lines)	Hatch cover for trunk in boatswain stores to forecandle deck is wasted and not watertight.

Ship Name: **KOELN EXPRESS**

IMO Number: **7502930**

Date Detained: **09/20/2002**

Port: **Charleston, South Carolina**

Ship Type: **Containership**

Flag: **Liberia**

Class Society: **Germanischer Lloyd**

Company(s): Owners, Operators or Managers
Falani Shipping Corp.

Deficiencies:	<u>Code - Category</u>	<u>Description</u>
	1730 - Oily-water separating equipment	Inoperable oily water separator.
	2110 - Oil/oily mixtures machinery spaces	Oily water mixture in bilge.
	1710 - Oil record book	Missing Lat/Long entries in Oil Record Book.

Ship Name:	LEVENTISA	Ship Type:	Bulk Carrier
IMO Number:	7210240	Flag:	Panama
Date Detained:	09/22/2002	Class Society:	Isthmus Bureau of Shipping
Port:	Port Everglades, Florida	Company(s):	<u>Owners, Operators or Managers</u> Bravo Ship Management Arthontisa Maritime, S.A.

Deficiencies:	<u>Code - Category</u>	<u>Description</u>
	0610 - Lifeboats	Port lifeboat rudder wasted and broken.
	0610 - Lifeboats	Port lifeboat mast mount and mast rope wasted and parted.
	0610 - Lifeboats	Missing port liferaft.
	0299 - Other (Crew)	Provide crew with proper safety equipment and clothing in accordance with the vessels SMS prior to conducting operations or sailing.
	1671 - Satellite EPIRB 406MHz/1.6GHz	Provide a registered 406 EPIRB on bridge.
	1699 - Other (radio)	GMDSS inoperable.
	1540 - Gyro compass	Gyrocompass inoperable.
	2515 - Company responsibility and authority	Objective evidence indicates that there is a failure in the Safety Management System. Vessel ordered to conduct an external audit.

Ship Name:	LIDA	Ship Type:	Containership
IMO Number:	7392907	Flag:	Antigua and Barbuda
Date Detained:	09/10/2002	Class Society:	Bureau Veritas
Port:	Ponce, Puerto Rico	Company(s):	<u>Owners, Operators or Managers</u> Jan Wind Shipping

Deficiencies:	<u>Code - Category</u>	<u>Description</u>
	0220 - Certificates of competency	Vessel's Master and Chief Mate could not provide STCW 95 endorsements from flag state.

Ship Name: **MARQUISE**

IMO Number: **7361128**

Date Detained: **09/18/2002**

Port: **N. Charleston, South Carolina**

Ship Type: **Bulk Carrier**

Flag: **Greece**

Class Society: **Lloyd's Register of Shipping**

Company(s): Owners, Operators or Managers
Marquimar Motor Ship Coproration
Navegadora Transpacifica S.A.

Deficiencies: Code - Category
2020 - Fire drills

2530 - Resources and Personnel

2550 - Maintenance of ship and equipment

Description

Crew unable to demonstrate proficiency in fire drill.

Chief officer not familirar with duties pertaining to the ship's Safety Management System.

Insufficient entries in log maintenance

Ship Name: **MIAMI SUPER**

IMO Number: **9012525**

Date Detained: **09/04/2002**

Port: **Miami, Florida**

Ship Type: **General Dry Cargo Ship**

Flag: **Panama**

Class Society: **Lloyd's Register of Shipping**

Company(s): Owners, Operators or Managers
International Maritime Ships Agents

Corp.

Miami Super Corp.

Deficiencies: Code - Category
0940 - Ballast fuel and other tanks

2545 - Reports/analysis of non-conformities, etc.

0230 - Number/composition (manning)

1575 - Echosounder

Description

Vessel has free communication between #2 starboard fuel oil tank and #3 starboard double bottom ballast tank. Crewmembers detected the contamination of fuel oil with water in #2 fuel oil tank in May 2002 with no action taken.

Vessel has outstanding non-conformities and outstanding conditions of class that have not been addressed.

Vessel not manned in accordance with the ship's Safe Manning Certificate. Three crewmembers have expired documents and one crewmember has no Panamanian documents.

Echo depth sounder is inoperable.

Ship Name: **MSC CHIARA**

IMO Number: **8420892**

Date Detained: **09/30/2002**

Port: **N. Charleston, South Carolina**

Ship Type: **Containership**

Flag: **Panama**

Class Society: **Det Norske Veritas**

Company(s): Owners, Operators or Managers
Cirsium Investments

Deficiencies: Code - Category
**1730 - Oily-water separating
Equipment**

Description
Oily water separator inoperable.

Ship Name: **RAVEN**

IMO Number: **8018223**

Date Detained: **09/22/2002**

Port: **Savannah, Georgia**

Ship Type: **Oil Tankship**

Flag: **Panama**

Class Society: **Nippon Kaiji Kyokai**

Company(s): Owners, Operators or Managers
Navis Maritime Corp

Deficiencies: Code - Category
0610 - Lifeboats

Description
The starboard lifeboat could not be started.

Ship Name: **REGAL EMPRESS**

IMO Number: **5262835**

Date Detained: **09/11/2002**

Port: **Portland, Maine**

Ship Type: **Passenger Ship**

Flag: **Bahamas**

Class Society: **Bureau Veritas**

Company(s): Owners, Operators or Managers
**International Shipping Partners
Regal Cruises Ltd**

Deficiencies: Code - Category
0960 - Means of escape

**0986 - Bulkheads - operational
damages**

0710 - Fire prevention

1099 - Other (alarm - signals)

0999 - Other (Safety In General)
**2515 - Company responsibility and
authority**

Description
**Emergency escape ladder by aft starboard
settling tank in engine room unusable.**

**Retaining stud on starboard shaft packing
missing and replaced with wooden shim.
Excessive egress of water in engineroom due to
this unsatisfactory temporary arrangement.**

**Diesel fuel leak on #3 generator fuel filter
assembly. Fuel spraying into machinery space.**

**Alarm's for watertight doors not working
properly.**

Raw sewage flowing into engine room bilge.

**Over 40 deficiencies discovered during
examination that give PSCO objective evidence
that there appears to be a breakdown in the
Safety Management System. Vessel ordered to
undergo an external audit.**

Ship Name: **SEVASTAKI**
IMO Number: **8218720**
Date Detained: **09/24/2002**
Port: **Mobile, Alabama**

Ship Type: **General Dry Cargo Ship**
Flag: **Liberia**
Class Society: **Germanischer Lloyd**
Company(s): Owners, Operators or Managers
Clipper Sea Transports Inc.
Columbia Shipmanagement Ltd.

Deficiencies:	<u>Code - Category</u>	<u>Description</u>
	2565 - Certification, verification and control	Objective evidence found via approximately 39 undocumented non-conformities discovered by PSCOs during the examination warrants vessel to undergo external audit.
	1240 - Cargo and other hatchways	Vessel has numerous wasted cargo hatches, hand rails, deck plate supports, quick acting watertight doors, and ventilation covers.
	1299 - Other (Load Lines)	Noted several large insets in way of vertical frames and numerous area with heavy pitting and corrosion on hull.
	0750 - Fire prevention	Numerous fuel and oil leaks were found in the generator room and main machinery space. Excessive oil and fuel in the bilges were noted. Pumps, gauges, gaskets on tank covers in the machinery space, and main/aux machinery were leaking excessively.

Ship Name: **SHALOM**
IMO Number: **7612280**
Date Detained: **09/11/2002**
Port: **Miami, Florida**

Ship Type: **General Dry Cargo Ship**
Flag: **Panama**
Class Society: **Honduras International Naval Surveying and Inspection Bureau**
Company(s): Owners, Operators or Managers
Macavol, Inc.
Shalom Oceanic, LTD.

Deficiencies:	<u>Code - Category</u>	<u>Description</u>
	0940 - Ballast fuel and other tanks	Vessel has a hole due to wastage in the tank top of the the double bottom ballast tank.
	0610 - Lifeboats	Vessel's lifeboats have multiple cracks.
	0680 - Embarkation arrangt. survival craft	Tiller for lifeboat is damaged.
	0610 - Lifeboats	Windows in wheelhouse are not watertight.

Ship Name: **SKY BULKER**
IMO Number: **9238210**
Date Detained: **09/07/2002**
Port: **Port Everglades, Florida**

Ship Type: **Bulk Carrier**
Flag: **Panama**
Class Society: **Nippon Kaiji Kyokai**
Company(s): Owners, Operators or Managers
Wealth Lines Inc.

Deficiencies: Code - Category
**0680 - Embarkation arrangt.
survival craft**

Description
Vessel was unable to recover port lifeboat due to inoperable davit release mechanism on lifeboat. Lifeboat fell 1.5 feet from above waterline into water while it was being recovered.

Ship Name: **WALKA MLODYCH**
IMO Number: **7637967**
Date Detained: **09/16/2002**
Port: **N. Charleston, South Carolina**

Ship Type: **Bulk Carrier**
Flag: **Malta**
Class Society: **Polski Rejestr Statkow**
Company(s): Owners, Operators or Managers
**Polska Zegluga Morska
Cepheus Shipping Ltd.
Polska Zegluga Morska**

Deficiencies: Code - Category
0720 - Fire fighting equipment

Description
Secondary firepump inoperable.

Ship Name: **YAMM**
IMO Number: **8313075**
Date Detained: **09/09/2002**
Port: **Corpus Christi, Texas**

Ship Type: **General Dry Cargo Ship**
Flag: **Malta**
Class Society: **Det Norske Veritas**
Company(s): Owners, Operators or Managers
**Sotramp Denizcilik Sanyı Ve Ticaret AS,

Gairloch Maritime Ltd.**

Turkey

Deficiencies: Code - Category
0220 - Certificates of competency

Description
All officers lacking valid endorsements from Flag state. Documentary proof of application for endorsements unavailable.